


### Typ A1


tolerance rozměrů:  $d_1, l_1 \pm 0,5 \text{ mm}$



$d_1$	$d_2$	$l_1$	maximální otáčky [ot./min.]
5	3; 2,35	12/20	76 430
6	3; 2,35	12/20	63 690
8	3; 2,35	12/20/25	47 770
10	3; 2,35	12/20/25	38 210
12	3; 2,35	12/20	31 840
10	6	15/20	38 210
12	6	15/20/30	31 840
15	6	15	23 880
16	6	25/35	23 880
20	6	15/25/35	23 880
25	6	25/35	15 280
30	6	30	11 940
32	6	25	11 940
40	6	25	9 550

### Typ A2

tolerance rozměrů:  $d_1, l_1 \pm 0,5 \text{ mm}$



$d_1$	$d_2$	$l_1$	maximální otáčky [ot./min.]
12	6	16	31 840
16	6	24	23 880
25	6	24	15 280
32	6	24	11 940